


FIGURE 5.—Damaged CE 135 windshield removed from the Presidential limousine, front view.



C.E. 399 8/23/78

FIGURE 6A.—CE 399, the fired 6.5-millimeter caliber full metal-jacketed bullet found on a stretcher in the emergency area of Parkland Memorial Hospital, side view.

liber Mannlicher-Carcano rifle, serial ft side.

DENCE
POLICE DEPT. WASH. D.C. 20001
TENE EXAMINATION SECTION

oer cartridge of Western Cartridge Cochamber of CE 139 rifie.

HSCA VII




FIGURE 6B.—CE 399, the fired 6.5-millimeter caliber full metal-jacketed bullet found on a stretcher in the emergency area of Parkland Memorial Hospital, view of the base portion, showing distortion.



Figure 7.—CE 542, a 6.5-millimeter caliber Mannlicher-Carcano rifle, serial No UC 5209, purchased by the FBI for comparison purposes.



4-15-78

MCL NUMBER CE 543

FIGURE 8A.—CE 543, one of three expended (of Western Cartridge Co. manufarture, re Texas School Book Depository, side view.



FIGURE 8B.—CE 543, one of three expended € of Western Cartridge Co. manufacture, r€ Texas School Book Depository, top view. case.

CE 543

43-377 O - 79 - 26